

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4229	DATE	Mar. 28, 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	In the front passenger airbag inflator of the subject light duty trucks, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABG-TRC600X	[HINO Dutro]	2013	1
TQG-XKC605M		2013	1
TQG-XKU600M		2013	2
TQG-XKU600X			
TQG-XKU605M		2013	5
TSG-XKU605M			
TQG-XKU640M		2013	1
TQG-XKU700M		2013	5
TQG-XKU710M		2013	5
TKG-XZC600M		2013	2
TKG-XZC605M		2013	70
TKG-XZC605Y			
TKG-XZC610T		2013	1
TKG-XZC645M		2013	6
TKG-XZC655M		2013	2
TKG-XZC675M		2013	5
TKG-XZC675T			
TKG-XZC710M		2013	11
TKG-XZU600E		2013	54
TKG-XZU600F			
TKG-XZU600M			
TKG-XZU600X			
TKG-XZU605M		2013	45
TKG-XZU610T		2013	3
TKG-XZU620T		2013	2
TKG-XZU640F		2013	27
TKG-XZU640M			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-XZU650F TKG-XZU650M	[HINO Dutro]	2013	6
TKG-XZU655M		2013	11
TKG-XZU675M TKG-XZU675T		2013	36
TKG-XZU685M		2013	41
TKG-XZU695M		2013	4
TKG-XZU700M		2013	37
TDG-XZU710M TKG-XZU710M		2013	45
TDG-XZU720M TKG-XZU720M		2013	39
TKG-XZU730M		2013	1
TKG-XZU775M		2013	5
NBG-BZU600 NBG-BZU600A	[Toyota Dyna 200] [Toyota Dyna 300]	2013	7
ABG-TRC600 ABG-TRC600A	[Toyota Dyna 400] [Toyota Toyoace G25]	2013	5
ABG-TRU600	[Toyota Toyoace G35]	2013	1
TQG-XKC605	[Toyota Toyoace G45]	2013	43
TQG-XKC655		2013	1
TQG-XKU600		2013	1
TQG-XKU605		2013	2
TQG-XKU655		2013	1
TQG-XKU710		2013	4
TQG-XKU720		2013	1
TKG-XZC600		2013	2
TKG-XZC605 TKG-XZC605V		2013	287
TKG-XZC610D		2013	7
TKG-XZC630D		2013	3
TKG-XZC645		2013	5
TKG-XZC655		2013	1
TKG-XZC675		2013	7
TKG-XZC710		2013	5
TKG-XZU600 TKG-XZU600A TKG-XZU600D TKG-XZU600H TKG-XZU600W		2013	36

