## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4226	DATE	Mar.30 2018		
MANUFACTURER	KATO WORKS CO.,LTD.				
DESCRIPTION OF DEFECT	For working device of the street sweepers, there is a possibility of interference between the gutter brush and the after-treatment device when you stow the brush with a relatively bigger angle than the specified since the range of motion for the right-hand side gutter brush has been incorrectly set up, therefore, it might have the after-treatment device worn by the rotating brush. If you continue to use the equipment with the same condition, you might have exhaust gas leaked from the device.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
TPG-NKR85N	ELF	$2015{\sim}2016$	6	2
		2015~2016	2	1)
TKG-NKR85N		2013~2014	2	2
		2016~2014	3	1)
SKG-NKR85N		2011	2	2
PDG-NKR85YN		2006~2010	2	1)
		2010	1	2
TKG-XZU640F	DUTRO -	2012~2016	16	2
		$2012\sim\!2017$	11	1
TKG-XZU640W		2012	1	1
SKG-XZU640F		2011~2012	2	2
		2012	1	1)
BDG-XZU378M		2011	1	1
BDG-XZU334M 改		2009~2011	8	2
BDG-XZU334M		2009	3	2
TKG-AKR85N	ATLAS	2012	1	2
TOTAL			62	