

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai- 2644	Date	April. 17, 2018
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )		
Description of defect	<p>Jaguar Land Rover has received Electronic Product Quality Reports (EPQRs) from dealers stating that on certain 2017 MY Land Rover Range Rover and Range Rover Sport vehicles the Thin Film Transistor (TFT) Instrument Cluster (IC) has been going blank intermittently. The instrument cluster will not display anything in this condition but will reset whilst driving. As such, these vehicles fail to comply with your National Regulations or United Nations Economic Commission for Europe (ECE) Regulation number 121-01 for a short period of time.</p> <p>Without the instrument cluster displaying important information such as the vehicle's speed, there would be an increased risk of a crash.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
ABA-LG3SB	「Range Rover」	2017	43
ABA-LG5SA	「Range Rover」	2017	60
ABA-LGL3SC	「Range Rover」	2017	6
ABA-LGL5SC	「Range Rover」	2017	21
ABA-LW3SA	「Range Rover Sport」	2017	55
ABA-LW5SA	「Range Rover Sport SVR」	2017	78
LDA-LG3KD	「Range Rover」	2017	127
LDA-LW3KB	「Range Rover Sport」	2017	103
Total			493