

VEHICLE SAFETY/POLLUSION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 2 6 0	DATE	JUNE 29, 2018
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO.,LTD		
DESCRIPTION OF DEFECT	<p>In the axle of the trailer, there is merging shortage of the welding in a part of vehicle because the execution management of the automatic welding machine that produces the axle is insufficient.</p> <p>Therefore when there is the case that a crack occurs on an axle and continues running in a state as is, in the case of the worst, a crack is worse, and there is a threat that an axle is damaged.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KA1962A	Pneumatic bulk tank semi-trailer	1994~1996	12
KA2142A	Pneumatic bulk tank semi-trailer	1995	4
KA2162C	Pneumatic bulk tank semi-trailer	1997	2
KA2213	Pneumatic bulk tank semi-trailer	1996	2
KA2262A	Pneumatic bulk tank semi-trailer	1995	1
KA2262C	Pneumatic bulk tank semi-trailer	1996~1997	29
KA2462A	Pneumatic bulk tank semi-trailer	1995~1997	30
KA2862	Pneumatic bulk tank semi-trailer	1996	2
KA2862A	Pneumatic bulk tank semi-trailer	1996	1
KA2962A	Pneumatic bulk tank semi-trailer	1995	3
KA3262	Pneumatic bulk tank semi-trailer	1995	1
TOTAL			87