

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4 3 7 5	DATE	N o v . 2 0 . 2 0 1 8
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>①The material of and machining condition for a radiator hose had been inadequate, so that some of the hoses concerned have short durability. Consequently, one of the hoses concerned may be damaged by the pressure of coolant and may leak coolant, and in the worst case, there is a real danger of overheating.</p> <p>②The manufacturing control for the spring of a shift shaft had been inadequate, so that some of the springs concerned have short durability. Consequently, one of the springs concerned may be damaged by repeated shift changing operations and there is a real danger that shift changing may become impossible in running.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RH07J	YZF-R3A	2015~2017	3,400
	MT320	2015~2017	1,880
2BL-RH13J	YZF-R3A	2017	80
	MT320	2017~2018	80
JBK-RG10J	YZF-R25	2014~2017	12,800
	YZF-R25A	2015~2017	3,480
	MT250	2015~2017	5,280
2BK-RG43J	YZF-R25	2017	480
	YZF-R25A	2017	240
	MT250	2017	120
		TOTAL	27,840