

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4376	DATE	December 6, 2018
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	Because the design of the main shift lever is inappropriate, some of the lever show a neutral position with the main shift entering 3rd gear. Therefore, if the operator enters the 3rd gear, the operator mistakes it as neutral position, and when the clutch is engaged, the tractor may start unintentionally.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-SL2B	SL38HQ	2017~2018	20
YDM-SL2B	SL38Q	2017~2018	6
YDM-SL2B	SL45HQ	2017~2018	29
YDM-SL2B	SL45Q	2017~2018	5
YDN-SL2C	SL54HQ	2017~2018	44
		TOTAL	104