

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

| | | | |
|-----------------------|---|------|------------|
| CAMPAIGN No. | Gai-2764 | DATE | 2018/12/13 |
| MANUFACTURE | Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | On certain E-Class vehicles (213 platforms) with 4-cylinder Diesel-engine OM 654 the routing of a fuel hose might not meet the specifications. In this case the fuel hose might come in contact with and subsequently chafe on the edge of a neighboring part. Continuous chafing might wear off the fuel hose material. This could lead in a first instance to a minor fuel leakage from the fuel hose, which would lead to clearly perceptible Diesel fuel smell. In the further course, drops of Diesel fuel might leak onto the underbody paneling and from there on the road. Only in case of long-time progress of the chafing resulting in increased leakage size, the engine might not be able to start and might stall during driving, respectively, due to pressure loss in the fuel line. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------------|---------------------|---------------------|-------------------|
| LDA-213004C | E220d | 2017 | 1642 |
| | | 2018 | 528 |
| LDA-213217 | E220d All-Terrain | 2018 | 114 |
| LDA-213204C | E220d Station Wagon | 2017 | 1147 |
| | | 2018 | 256 |
| | | TOTAL | 3687 |