VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4452	DATE	February 28 ,2019
MANUFACTURER	NIPPON TREX CO.,	LTD.	
DEFECT	Regarding the wheel for single tire for semi-trailer, scratches occurs on some of the wheels due to inadequate manufacturing process management. Therefore, cracks will be occurred because of the scratches as a starting point, and air leakage occurs, and in the worst case, there are possibility that the vehicle not be able to continue to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CTB32003	_	2013~2014	4
CTB320GL	_	2013~2014	4
CTB34003	_	2013~2014	3
CTD320AC	_	2013	1
CTS34001	_	2013~2014	6
CTS34003	_	2013~2014	3
PFB34111	_	2014	4
PFB34113	_	2014~2015	3
PFB34117	_	2014	11
PFB34118	_	2014	2
PFV341AJ	_	2014	1
PFW342NJ	_	2014	2
TNF32511	_	2013~2015	24
TNF325AN	_	2013	1
TNF325AP	_	2013	4
TNF325AU	_	2013	1
TNF326AC	_	2013	1
TNF326AD	_	2013~2014	4
VFD345AA	_	2013	5
VFR245AH	_	2014	6
VFR344AB	_	2013	20
VFR344AC	_	2014	10
VFR348AB	_	2013	4
VPD341AB	_	2014	3
KTT241S	_	2013	3
NT30C010	_	2014	1
NTCTB34003	_	2014~2015	2
		TOTAL	133