

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 2854	DATE	14 June, 2019
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that moisture can get into the control unit for the air-conditioning blower on the affected vehicles. Moisture that seeps in can cause malfunctions and short circuits in the air-conditioning blower control system. These short circuits can cause a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-970M46	Panamera	2011	37
		2012	236
		2013	199
	Panamera 4	2011	39
		2012	91
		2013	65
ABA-970M46A	Panamera	2011	7
		2012	12
		2013	9
	Panamera 4	2011	6
		2012	8
		2013	3
ABA-970M48A	Panamera S	2011	45
		2012	76
		2013	36
	Panamera 4S	2011	57
		2012	98
		2013	21
	Panamera Turbo	2011	42
		2012	16

ABA-970M48A	Panamera Turbo	2013	11	
	Panamera GTS	2013	253	
ABA-970M48TA	Panamera Turbo S	2012	20	
		2013	2	
DAA-970CGEA	Panamera S hybrid	2012	151	
		2013	41	
ABA-970CWA	Panamera	2014	209	
		2015	166	
		2016	324	
	Panamera 4	2014	52	
		2015	31	
		2016	47	
ABA-970CWAA	Panamera	2014	11	
		2015	18	
		2016	33	
	Panamera 4	2014	10	
		2015	3	
		2016	4	
ABA-970CWBA	Panamera Turbo	2014	19	
		2015	11	
		2016	7	
	Panamera Turbo S	2014	1	
		2015	3	
		2016	3	
ABA-970CWBAX	Panamera Turbo	2014	5	
		2015	2	
	Panamera Turbo S	2014	1	
		2016	2	
	Panamera S	2014	79	
ABA-970CWDA		2015	35	
		2016	22	
		2014	62	
		2015	33	
		2016	11	
ABA-970CWDAX	Panamera 4S	2015	3	

ABA-970CWDAX	Panamera 4S	2015	1
		2016	3
ABA-970CXPA	Panamera GTS	2014	124
		2015	132
		2016	92
ALA-970CGEA	Panamera S e-hybrid	2014	93
		2015	115
		2016	94
		TOTAL	3431