

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4548	DATE	Aug.6 2019
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks and buses equipped with air suspension, since the setting of the springs holding the rear brake shoes is inappropriate, the shoes may vibrate due to the vibration input during traveling and hit the clips (the parts holding the shoe clearance adjusters), resulting in deformation or damage of the clips. If the vehicle continues to be used in this condition, the shoe clearances may increase and, in the worst case, the braking force of the rear brakes may decrease.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-FV64VJR	「FUSO SUPER GREAT」	2016~2017	43
QPG-FP64VDR		2015~2018	1,750
QPG-FP64VER		2016~2018	467
QPG-FP64VGR		2016~2018	135
QPG-FU64VY		2016~2017	92
QPG-FU64VZ		2015~2017	2,226
QPG-FU65VZ		2015~2017	249
QPG-FV64VJR		2016~2017	20
QPG-FV64VZ		2016~2017	211
2KG-FV74HJR		2018~2018	28
2PG-FP74GGR		2018~2019	16
2PG-FU74GY		2017~2019	46
2PG-FU74GZ		2017~2019	154
2PG-FU74HY		2017~2019	90
2PG-FU74HZ		2017~2018	2,148
2PG-FU75GZ		2017~2018	3
2PG-FU75HZ		2017~2019	375
2PG-FV74GZ		2017~2019	23
2PG-FV74HJR		2018~2018	15
2PG-FV74HZ		2017~2019	293
2RG-FP74HDR		2017~2019	894
2RG-FP74HER		2017~2019	378
2RG-FP74HGR		2017~2019	58
QDG-MM97FH	「FUSO AERO ACE」	2016~2017	45
QTG-MS96VP	「FUSO AERO QUEEN」	2016~2017	1,099
TDG-MM97FH	「FUSO AERO ACE」	2016~2017	231
2TG-MS06GP	「FUSO AERO ACE」	2017~2019	1,029
	「FUSO AERO QUEEN」	2017~2019	185
		TOTAL	12,569