

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|------|---------------|
| CAMPAIGN No. | 4574 | DATE | Sep.30th 2019 |
| MANUFACTURER | NIPPON SHARYO.LTD. | | |
| DESCRIPTION OF DEFECT | <p>On tank vehicles, due to inappropriate construction of the design mounting the pressurized evaporator on vehicle frame, the stress brought by the vehicle running, so the cracks may occur the frame of the pressurized evaporator.</p> <p>So, if the vehicles are continued to run without the repairing, at worst case, the pressurized evaporator come off and it may become to be impossible that the vehicles run.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|------------|-------------------------------------|--|--------------------|
| ATL123-LNG | 12.3ton LNG tank semi-trailer | ATL123LNG-1~45 Nov.3 2003~Sep.21 2007 | 38 |
| TOTAL | | | 38 |

(Caution) The range of vehicle base numbers for vehicles that are recalled may include vehicles that are not eligible.