

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4591	DATE	October 24 ,2019
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>In the integrated controller in the bus, the control program for the door anti-trap function is inappropriate. Consequently, if the accelerator pedal is depressed as the door is closing, the door anti-trap system may be deactivated, causing the passengers to get trapped in the door.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-LV290N3 2KG-LV290N3 2PG-LV290N3	[ERGA]	2019	27
2PG-LV290Q3		2019	2
2KG-LR290J4	[ERGA MIO]	2019	2
		TOTAL	31