

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2956	DATE	2019/11/21
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain C-Class, E-Class vehicles (205, 213 platforms) with rear-wheel drive a locknut in the steering rack might exhibit cracks. In the very improbable case that a pre-damaged locknut was installed in a vehicle, this locknut might break due to exposure of the steering to very high lateral forces, which can occur for example in case of contact with the curb during maneuvering or parking. In consequence, rotating components inside the steering rack might contact the housing, leading to a blocking of the steering. In this case, the risk of a crash is increased.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-205040C	C180	2015	1	
RBA-205042	C200		19	
RBA-205042C		2017	1	
		2018	1	
		2015	7	
RBA-205045		C250	2016	1
			2017	2
	2015		5	
RBA-213042C	E200	2017	1	
LDA-213004C	E220d		3	
RBA-213045C	E250		2	
DBA-205240C	C180 Statiowagon	2015	1	
		2018	1	
RBA-205242	C200 Statiowagon	2015	3	
		2016	3	
		2017	4	
		2018	3	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-205242C	C200 Statiowagon	2015	2
		2017	1
RBA-213242C	E200 Statiowagon		
RBA-238442C	E200 Cabriolet	2018	1
		TOTAL	64