

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicle

CAMPAIGN No.	4633	DATE	Jan. 09, 2020
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO.,LTD		
DESCRIPTION OF DEFECT	Due to lack of durability of the bearing for hydraulic line selecting area on the hydraulic pump which is used for winch hoisting and propelling on a wheel crane, the bearing might be broken with load which is generated at idling during crane working mode. Consequently, propelling direction (forward / backward) of the machine might not be changed because hydraulic line cannot be changed properly.		
Countermeasure	The hydraulic pump would be replaced with an improved one.		
Method for informing the concerned parties	<ul style="list-style-type: none"> <li>▪ User: Be announced with direct mail or visiting.</li> <li>▪ Work shop for automobile wrecking and maintenance: Announce the an authorized service shops of Kobelco</li> <li>▪ Stick a sticker No.4633 around a striker of a door on a cabin after the modification is completed.</li> </ul>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-EE02	RK250-7	EE02-11001 ~ EE02-11095 Feb. 03, 2011 ~ Mar. 25, 2013	86 units
TOTAL			86 units