

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4643	DATE	January 16 ,2020
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Regarding the seat belt for the truck's passenger seat, due to improper adjustment made to the assembly equipment, there are cases where a spring in the retractor locking mechanism is assembled at an angle. Consequently, the said spring may interfere with a retractor component, potentially causing the mechanism not to lock when the seat belt is pulled out quickly.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CVR60C	[GIGA]	2019	1
2KG-CXE77C 2PG-CXE77C		2019	5
2KG-CXM60CT		2019	2
2KG-CXM77C		2019	1
2KG-CXY77CJ		2019	1
2KG-CXZ60CT		2019	4
2KG-CXZ77CT 2PG-CXZ77CT		2019	81
2KG-CYE60CM		2019	12
2KG-CYG60CM		2019	6
2PG-CYH77C		2019	7
2KG-CYJ77C 2KG-CYJ77CA 2PG-CYJ77C 2PG-CYJ77CA		2019	256
2DG-CYJ77CW		2019	4
2KG-CYJ77CZ 2PG-CYJ77CZ		2019	7
2KG-CYL77C 2PG-CYL77C 2PG-CYL77CA		2019	65
2PG-CYL77CM		2019	4
2PG-CYL77CZ		2019	4

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CYM77C 2PG-CYM77C	[GIGA]	2019	7
2KG-CYM77CM 2PG-CYM77CM		2019	9
2KG-CYY77C 2PG-CYY77C		2019	5
2PG-CYY77CJ		2019	1
2KG-CYY77CY 2PG-CYY77CY		2019	3
2DG-CYZ52CMQ		2019	4
2DG-CYZ52CV		2019	1
2KG-CYZ77C 2PG-CYZ77C		2019	12
2KG-CYZ77CJ		2019	1
2PG-CYZ77CM		2019	11
2DG-CYZ77CMQ		2019	1
2DG-CYZ77CV		2019	1
2KG-EXD52CD 2PG-EXD52CD		2019	63
2PG-EXD52CE		2019	3
2PG-EXD52CG		2019	1
2PG-EXD77CD		2019	2
2PG-EXD77CG		2019	3
2DG-EXY52CK 2PG-EXY52CK		2019	2
2DG-EXZ52CK		2019	10
2PG-FRR90S1 2PG-FRR90S2 2PG-FRR90T2 2RG-FRR90S1 2RG-FRR90S2 2RG-FRR90T2		[FORWARD]	2019
2RG-FRS90S2	2019		9
2PG-FSR90S2 2PG-FSR90T2 2RG-FSR90S2 2RG-FSR90T2	2019		84

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FSS90S2 2RG-FSS90S2	[FORWARD]	2019	7
2PG-FTR90U2 2PG-FTR90V2 2RG-FTR90U2 2RG-FTR90V2		2019	113
2PG-FVR90U2		2019	5
2KG-FVZ60U2		2019	49
2KG-FVZ90U2		2019	1
2RG-NHR88A 2RG-NHR88AN		[ELF]	2019
2RG-NHS88A 2RG-NHS88AN	2019		33
TFG-NJR82AN	2019		1
2RG-NJR88A 2RG-NJR88AD 2RG-NJR88AN 2RG-NJR88N	2019		187
2RG-NJS88A 2RG-NJS88AN	2019		23
2PG-NKR88N 2RG-NKR88A 2RG-NKR88AD 2RG-NKR88AN 2RG-NKR88AR 2RG-NKR88N 2RG-NKR88R	2019		290
2PG-NKR88YN 2RG-NKR88YN	2019		13
2PG-NKS88AD 2PG-NKS88AN 2RG-NKS88A 2RG-NKS88AN	2019		38
2RG-NLR88AN 2RG-NLR88AR 2RG-NLR88N 2SG-NLR88AN	2019		188
2RG-NLS88AN 2RG-NLS88AR	2019		21
TFG-NMR82ZAN	2019		11

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-NMR88R 2RG-NMR88AN 2RG-NMR88AR 2RG-NMR88N 2RG-NMR88R 2SG-NMR88AN	[ELF]	2019	200	
2PG-NMS88AN 2RG-NMS88AN 2RG-NMS88AR		2019	47	
2RG-NNR88AN 2RG-NNR88AR		2019	17	
2RG-NNS88AN		2019	1	
2PG-NPR88AN 2PG-NPR88AR 2PG-NPR88N 2RG-NPR88AN 2RG-NPR88AR 2RG-NPR88N 2SG-NPR88AN		2019	456	
2PG-NPR88YN 2RG-NPR88YN		2019	198	
2PG-NPS88AN 2PG-NPS88AR 2RG-NPS88AN 2RG-NPS88AR		2019	49	
2RG-AHS88A		[ATLAS]	2019	1
2PG-BRR90S2 2PG-BRR90T2 2RG-BRR90S2 2RG-BRR90T2		[CONDOR]	2019	39
2PG-BRS90S2	2019		2	
2RG-BSR90S2	2019		2	
2PG-BTR90U2 2RG-BTR90U2 2RG-BTR90V2	2019		6	
2KG-BVZ60U2	2019		5	
			TOTAL	3,622

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Seat Belt	8-97426866-0	2019	2
	8-97428435-0	2019	1
	8-97428457-1	2019	2
	8-97428932-0	2019	7
	8-97468078-0	2019	2
		TOTAL	14