

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2970	DATE	January 22, 2020
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On power steering oil cooler, swage parts of union pipes are incorrectly manufactured because of incorrect instruction by the supplier. Therefore, the hoses could be detached when high system pressure is applied and power steering system oil will leak resulting in loss of power steering assist function, in the worst case, it could lead to vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
Unknown	Continental Supersports	2017	10