

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2974	DATE	January 22 <sup>nd</sup> , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>There have been indications that this type of gas generator can leak in the long term. This leak enables the propellant in the gas generator to absorb moisture. A high moisture absorption and re-drying over longer periods of time can lead to a breakdown of the propellant.</p> <p>In this case, in the event of an accidental airbag deployment, a very high internal pressure in the gas generator can occur and in the worst case it can burst the gas generator and metal parts can cause possibly injuries.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-AL19	BMW 318i	1998 - 2000	4987
	BMW 318i Touring	2000	2
GF-AM20	BMW 320i	1999 - 2000	984
GF-AM25	BMW 323i	1998 - 1999	2805
GF-AM28	BMW 328i	1998 - 1999	1940
	BMW 328Ci	1998 - 1999	245
Total			10,963

Vehicles which may have received a replacement driver air bag as part of a vehicle repair.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-AL19	BMW 318i	1999 - 2000	3,592
	BMW 318i Touring	1999 - 2000	511
	BMW 318Ci	1999 - 2000	758
GH-AL19	BMW 318i	2020	4
GF-AM20	BMW 320i	1999 - 2000	4,512
GF-AM25	BMW 323i	1999 - 2000	1,416
GF-AM28	BMW 328i	1999 - 2000	518
	BMW 328Ci	1999 - 2000	559
GH-AV30	BMW 330i	1999 - 2000	2
	BMW 330Ci	2020	4
Total			11,876