## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| CAMPAIGN No.             | GAI-2972   | DATE | January 23, 2020 |
|--------------------------|--|------|------------------|
| MANUFACTURER             | HONDA OF AMERICA MFG., INC.  |      |                  |
| DESCRIPTION OF<br>DEFECT | Driver's airbag inflator is inadequately prevented from absorbing moisture whereby<br>gas generating propellant contained therein may absorb moisture. Should gas<br>generating propellant be moisturized and dried repeatedly while the vehicle<br>continues in service, the inflator could fail to properly inflate the airbag in the event<br>of airbag deployment. |      |                  |

| TYPE   | COMMERCIAL           | MODEL YEAR | NUMBER OF |
|--------|----------------------|------------|-----------|
|        | NAME                 | RECALLED   | VEHICLE   |
| GF-UA4 | 「INSPIRE」<br>「SABER」 | 1998~1999  | 943       |
| GF-UA5 |                      |            | 459       |
|        |                      | TOTAL      | 1,402     |