

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2971	DATE	Jan. 29, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	The fluid may leak out of the return hose for the hydraulic power steering. The return hose for the hydraulic power steering must be replaced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4HCDRF	Audi A8 4.2q	2011-2012	471
ABA-4HCDRL	Audi A8L 4.2q	2011-2012	99
ABA-4HCEJL	Audi A8 6.3q	2011-2013	38
ABA-4HCEUF	Audi A8 4.0 Tq	2013	191
ABA-4HCEUL	Audi A8L 4.0 Tq	2013	54
ABA-4HCGTF	Audi S8	2013	154
ABA-4HCGWF	Audi A8 3.0Tq	2011-2012	149
DBA-4HCGWF	Audi A8 3.0Tq	2012-2013	257
		Total	1,413