

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI -2976	DATE	29th/Jan/2019
MANUFACTURE	LOTUS CARS Plc (Japanese Importer :LCI Limited)		
DESCRIPTION OF DEFECT	On Elise cars fitted with superchargers, the plastic spacer used to hold the fuel rail above the engine may become deformed due to heat and/or vibrations, causing the mounting bolt to loosen or fail. This could lead to the fuel rail moving and thus the seal at the injector mounting being breached, causing fuel leakage and, in a worst case scenario, fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LOTUS	ELISE SPORT/SPRINT 220	2012~2020	514
	ELISE CUP 250	2019	25
		TOTAL	539

【記入例】

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

輸入車のリコールの場合、Import に丸印を記入するか、Domestic に二重線を記入又は記載しない用にして下さい。

CAMPAIGN No.	GAI-	DATE	Domestic / Import Vehicles July 21, 2005
MANUFACTURE	(Japanese Importer :)		
DESCRIPTION OF DEFECT	<p>上段には自動車製作者の名称を記載して下さい。 下段には届出者の名称を記載して下さい。</p> <p>日付の記載は、月（英字）日（アラビア数字）、西暦の順でリコール届出年月日を記載して下さい。（リコール開始年月日を記入しないで下さい。）</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
		製作年のみの記載。 2005-2006	
		TOTAL	

Domestic Vehicles : 日本国内車両

Import Vehicles : 輸入車両

CAMPAIGN No. : 届出番号

DATE : 届出年月日

MANUFACTURE : 製作者名

DESCRIPTION OF DEFECT : 不適合状態

TYPE : 型式

COMMERCIAL NAME : 通称名

MODEL YEAR RECALLED : 対象車両の製作年

NUMBER OF VEHICLE : 対象車両数