

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4663	DATE	Feb.12.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the quarter window glass molding mounted at the rear part of the rear door, due to improper primer used for adhesion to the glass, there is a possibility that the molding could peel from the quarter window glass due to the stress generated by repeated temperature fluctuations. In this condition, a gap may develop between the molding and the quarter window glass, causing abnormal noise. In the worst case, the molding could detach from the quarter window glass.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
6AA-AZSH20	[CROWN]	2018-2019	15,677	RS grade
6AA-AZSH21			2,284	
6AA-GWS224			1,469	
3BA-ARS220			1,149	
		TOTAL	20,579	