

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4656	DATE	February 18, 2020
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	An accelerator pedal spring may rust in the use of the forklift truck due to improper surface treatment of the external spring. Therefore, continued use under the condition might cause damage to the spring, and in the worst case, the accelerator pedal may not return to normal position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
211AC	「TRANSER」	2000 ~ 2016	34
ZAF-211AC		2016 ~ 2018	15
—		2018	1
		TOTAL	50