

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4671	DATE	February 26, 2020
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	In the hydraulic circuit of skid-steer loader, since the selection of hydraulic oil is inappropriate, so that strange noise may be occurred because of the roller and/or the cam ring worn in HST motors. If the truck is continued running, HST motors could not be turning around, and in the worst case the truck might not be able to run again as a result.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDM-B14	SL7	2016	13
	SL9	2017	
		2018	
		TOTAL	13