

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2988	DATE	Feb 26. 2020
MANUFACTURE	LIEBHERR (Japanese Importer : Liebherr-Japan Co.,LTD.)		
DESCRIPTION OF DEFECT	Some of the crane axle knuckle have insufficient thickness. For this reason, cracks occur in the relevant part during clean work, in the worst case, the knuckle is damaged and normal steering may not be possible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
unknown	LTM11200NX	10 Jul 2015 ~ 03 Jul 2017	5 units
unknown	LTM1550N	01 Dec 2015 ~ 28 Feb 2016	2 units
unknown	LTM1220NX-2	01 Jun 2015 ~ 15 Oct 2015	2 units
		TOTAL	9 units