

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4675	DATE	Feb. 27. 2020
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain air circuits for brake operation of heavy duty trucks, due to insufficient durability evaluation of the air tank for regenerating the desiccant, the air tank may crack, causing a leak of air. Therefore, an air leak noise may be made or the alarm buzzer may operate, resulting the brake effectiveness to deteriorate if it is continued to be used under the condition.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FS1AJA	[HINO Profia]	2019	1
		TOTAL	1