## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN NO.	4679	DATE	February 27 ,2020
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the heavy duty truck that runs on compressed natural gas (CNG), there are some where the inappropriate control of the main stop valve causes vibration when the fuel gas is filled, resulting in cracks on the fuel pipe. Consequently, such cracks may grow as refueling is repeated, possibly leading to fuel leak.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
QFG-CYJ78B	[GIGA]	2017-2019	9
QFG-CYL78B		2016-2018	8
		TOTAL	17