VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2989	DATE	%Feb 27, 2020	
MANUFACTURE	Automobiles PEUGEOT			
	Automobiles CITROEN			
	(Japanese Importer :	Groupe PSA Japan Co.,L	td.)	
DESCRIPTION OF	On affected vehicles, Some AdBlue tank caps do not have ventilation holes, and the inside of the AdBlue tank becomes negative pressure during the use process, which may deform the AdBlue tank. Further, when the pressure inside the AdBlue tank becomes negative, the load on the AdBlue priming pump increases, and the warning light is turned on and a message is displayed. In the worst case there is a possibility of not conforming to Emission regulation.			
DEFECT				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-T9AH01	「308」	2013-2017	22
LDA-T9BH01	「308」	2013-2017	149
LDA-T9WAH01	「308」	2013-2017	2
LDA-T9WBH01	「308」	2013-2017	115
LDA-W2AH02	「508」	2013-2017	79
LDA-W2WAH02	「508」	2013-2017	102
LDA-B787AH01	「C4 Picasso」	2013-2017	1
LDA-B7BH01	「C4」	2013-2017	16
LDA-B7CAH02	「DS4」	2013-2017	17
LDA-B8AH02	「DS5」	2013-2017	4
		TOTAL	507