

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2990	DATE	March 2 <sup>nd</sup> , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	It cannot be ruled out that, due to long-term influences in areas with a high level of air humidity, moisture gets into the housing of the gas generator on the front-side front passenger airbag caused by possibility of an inflator manufacturing error. In this case, if the front passenger airbag is activated, there may be an increased volume of internal pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-AT18	BMW 316ti	2001 - 2004	509
GF-AL19	BMW 318i	1999 - 2000	700
	BMW 318i Touring	1999 - 2000	268
	BMW 318Ci	1999 - 2000	205
GH-AL19	BMW 318i	2000 - 2001	1,351
	BMW 318i Touring	2000 - 2001	473
	BMW 318Ci	2000 - 2001	233
GH-AY20	BMW 318i	2001 - 2004	6,817
	BMW 318i Touring	2001 - 2005	3,053
	BMW 318Ci	2001 - 2005	946
GH-BX20		2005 - 2006	320
GH-AU20	BMW 318ti	2001 - 2004	900
GF-AM20	BMW 320i	1999 - 2000	1,029
GH-AV22		2000 - 2004	9,143
GF-AM25	BMW 323i	1999 - 2000	356
GH-AV25	BMW 325i	2000 - 2004	1,817
	BMW 325i Touring	2000 - 2005	1,101
GF-AM28	BMW 328i	1999 - 2000	146
	BMW 328Ci	1999 - 2000	119

GH-AV30	BMW 330i	2000 - 2006	2,107
	BMW 330Xi	2001 - 2004	69
	BMW 330Ci	2000 - 2006	785
	BMW 330Ci Cabriolet	2000 - 2003	586
GF-BL32	BMW M3	2001 - 2002	603
GH-BL32		2001 - 2006	1,269
GH-M3CSL	BMW M3 CSL	2003	116
Unknown	BMW M3 Cabriolet	2002	1
TOTAL			35,022

**【Note】**

This recall affects vehicles which already had a replacement of the relevant airbags due to Recalls Gai-1933 (notified on 20.05.2013) and Gai-2080 (notified on 05.09.2014) and received again an airbag containing ammonium nitrate without desiccant.