

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2991	DATE	March 2, 2020
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	It cannot be ruled out that, due to long-term influences in areas with a high level of air humidity, moisture gets into the housing of the gas generator on the front-side front passenger airbag caused by possibility of an inflator manufacturing error. In this case, if the front passenger airbag is activated, there may be an increased volume of internal pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-3E44	B3-3.3	1999-2000	51
GF-3E44	B3-3.3 Coupe	2000	9
GF-3E46	B3-3.3	2001-2002	68
GF-3E46	B3-3.3 Coupe	2001-2002	24
GF-3E46	B3-3.3 Cabrio	2001-2002	16
GF-3E46	B3-3.3 Touring	2001-2002	16
GF-3E48	B3-3.3 4WD	2002-2003	4
GF-3E48	B3-3.3 4WD Touring	2002	15
GH-3E48	B3-3.3 4WD	2004-2005	2
GH-3E48	B3-3.3 4WD Touring	2002-2004	15
GH-3E50	B3S	2003-2005	124
GH-3E50	B3S Coupe	2003-2006	35
GH-3E50	B3S Cabrio	2003-2006	14
GH-3E50	B3S Touring	2002-2004	16
GH-3E51	B3S	2003-2004	23
GH-3E51	B3S Coupe	2003-2005	5
GH-3E51	B3S Cabrio	2004-2005	6
GH-3E51	B3S Touring	2003-2004	3
		TOTAL	446