

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

| | | | |
|-----------------------|---|------|-----------------|
| CAMPAIGN No. | Gai-2992 | DATE | March 2nd, 2020 |
| MANUFACTURER | BMW (Japanese Importer: BMW Group Japan Corp.) | | |
| DESCRIPTION OF DEFECT | Due the body domain controller's program is inappropriate, even when the taillight is turned on alone while the daytime running lights are on, the required display in the instrument cluster's indicator light is not displayed. For this reason, there is a possibility that it does not comply with the Japanese Safety Regulation Article 37(standard of taillights). | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|------------------|---------------------|-------------------|
| 3BA-7K15 | BMW 118i | 2019 | 2,269 |
| 3BA-7L20 | BMW M135i xDrive | 2019 | 446 |
| | | TOTAL | 2,715 |