

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4683	DATE	Mar.4.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the fuel pump impeller, due to an improper injection molding process, the resin density of some impellers may be low and they deform by absorption of excessive fuel. If this were to occur, the impeller may interfere with the fuel pump body and fuel pump becomes inoperative, and in the worst case, resulting in engine stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRR80W	[NOAH] [VOXY]	2014	16,273
DBA-ZRR80W “Kai”(modified)			
DBA-ZRR85W		2014	
DBA-ZRR80G	[NOAH] [VOXY] [ESQUIRE]	2014	11,384
DBA-ZRR80G “Kai”(modified)			
DBA-ZRR85G		2014	3,556
DBA-ZRR85G “Kai”(modified)			
DBA-ARS210	[CROWN]	2017-2018	690
3BA-ARS220		2018	2,503
DAA-GWS214		2013-2015	7,990
6AA-GWS224		2018	5,174
DBA-GGH30W		[ALPHARD] [VELLFIRE]	2017-2018
DBA-GGH35W		2017-2018	2,572

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-GSJ15W	[FJ CRUISER]	2013-2015	4,631
CBA-URJ202W	[LAND CRUISER]	2013-2015	3,793
CBA-GRJ150W	[LAND CRUISER PRADO]	2013-2015	783
CBA-GRJ151W		2013-2015	608
DBA-USF40	[LS460]	2013-2015	3,064
DBA-USF45		2013-2015	165
DBA-USF41	[LS460L]	2013-2015	173
DBA-USF46		2013-2015	35
DBA-VXFA50	[LS500]	2017-2018	4,249
DBA-VXFA55		2017-2018	919
DAA-GVF50	[LS500h]	2017-2018	4,848
DAA-GVF55		2017-2018	4,666
DAA-UVF45	[LS600h]	2013-2015	2,781
DAA-UVF46	[LS600hL]	2013-2015	763
DAA-GYL20W	[RX450h]	2017-2018	2,494
DAA-GYL25W		2017-2018	3,768
DAA-GYL26W	[RX450hL]	2017-2018	1,677
DBA-AGZ10	[NX200t]	2014-2015	3,210
DBA-AGZ15		2014-2015	1,730
DBA-GRL11	[GS250]	2013-2015	356
DBA-ARL10	[GS300]	2017-2018	245
DBA-GRL10	[GS350]	2013-2015	666
DBA-GRL12		2017-2018	266

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GRL15	[GS350]	2013-2015	313
DBA-GRL16		2017-2018	170
DAA-GWL10	[GS450h]	2013-2015	1,880
DBA-URZ100	[LC500]	2017-2018	1,454
DAA-GWZ100	[LC500h]	2017-2018	737
DBA-ASE30	[IS200t] [IS300]	2017-2018	1,136
DBA-GSE31	[IS350]	2013-2018	1,006
DBA-USE20	[IS F]	2013-2014	118
DBA-ASC10	[RC200t] [RC300]	2017-2019	514
DBA-GSC10	[RC350]	2014-2018	666
		TOTAL	113,302