

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 6 8 2	DATE	Mar.5.2020
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the hybrid power train control module(HPCM) of hybrid vehicle, due to inappropriate motor driving force control program, communication abnormality with engine control unit (ECU) occurs and then if fail-safe mode activate, the driving power is not transmitted and it may be unable to drive temporarily.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HNT32	X-TRAIL	2017	20,357
DAA-HT32		~ 2019	6,551
		TOTAL	26,908