

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 6 8 5	DATE	March. 12. 2020
MANUFACTURER	TRANTECHS. CO. , LTD		
DESCRIPTION OF DEFECT	In horizontal suspension spare tire carriers for medium trucks, the shape of the hanging plate is inappropriate, when a tire with an aluminum wheel is fixed to the carrier, spare tires may rotate due to vibration while moving. For that reason, the spare tire carrier chain and suspension plate can scrape together potentially causing the spare tire carrier chain to break and in the worst-case scenario, the spare tires may fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-NPR85AN	ELF	2012~2019	109
TKG-NPR85AN			
TPG-NPR85AN			
TRG-NPR85AN			
SKG-NPR85YN		2012~2017	6
TKG-NPR85YN			
2PG-NPR88YN		2018	8
		TOTAL	123