

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4688	DATE	March 13,2020
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The rear wheel hub of the forklift truck has a problem of lack of strength due to improper instructions for the manufacturing process. Therefore, if the forklift truck is kept being driven under such circumstances, it may be broken and the rear tires fall off in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-M289	「FH100-1 FH120-1 FH135-1 FH160-1」	2018-2019	15
		TOTAL	15