

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4691	DATE	Mar. 17, 2020
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the insufficient control program of the lane departure prevention function, the lane departure warning does not work even when the system detects the vehicle deviation from the running lane, in case the driver has turned off the lane departure warning function.</p> <p>The above situation does not conform to the article 11 of the safety standard (Steering system standard) of Japanese road transportation vehicle law.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
4AA-MR52S	HUSTLER	2019~2020	2,971
4AA-MS52S	FLAIR CROSSOVER	2020	122
		TOTAL	3,093