

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2994	DATE	March 17 th , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to an incorrect heat treatment of the rear right wheel rim, there may be a crack in the spokes. This may not comply with the Japanese safety regulation article 9.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-2Z15	BMW i8	2017 - 2018	3
CLA-2Z15U	BMW i8 Roadster	2018	3
		TOTAL	6