

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	GAI-3001	DATE	March 17 th , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>The fault involves the Exhaust Gas Recirculation (EGR) Module of diesel engine. Part of this module is the EGR cooler, which can become leaky due to insufficient durability.</p> <p>The leaking coolant could create in combination with soot and oil sediments in the EGR module ignitable deposits. Through exposure to high exhaust gas temperature this could result in melting of the intake manifold and a consequent to loss of engine power, lighting of engine check lamp and thermal incident as a worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-1S20	BMW 118d	2017	2
LDA-2C20	BMW 218d ActiveTourer		1
LDA-8C20	BMW 320d		27
LDA-JC20	BMW 523d		1
LDA-JM20	BMW 523d Touring		1
LDA-HT20	BMW X1 xDrive 18d		1
LDA-WY20	BMW X3 xDrive 20d		3
LDA-TX20			
LDA-XN15	MINI Cooper D		140
LDA-XT15	MINI Cooper D 5 Door		221
		TOTAL	397