

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3006	DATE	March 17, 2020
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	The fault involves the Exhaust Gas Recirculation (EGR) Module of diesel engine. Part of this module is the EGR cooler, where coolant can become leaky due to insufficient durability of this component. The leaking coolant could create in combination with soot in the EGR module which may consequently become an ignitable deposits through exposure to high exhaust gas temperature, resulting in melting of the intake manifold and a consequent to loss of engine power, lighting of engine check lamp and thermal incident as a worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FDA-3P10	D3 Biturbo	2016-2017	118
	D3 Biturbo Touring	2016-2017	46
	D4 Biturbo Coupe	2015-2018	33
FDA-PP10	XD3 Biturbo	2015-2017	74
FDA-MP20	D5 Turbo	2015-2016	28
		TOTAL	299