

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 6 8 4	DATE	March.18.2020
MANUFACTURER	TOYOTA CUSTOMIZING & DEVELOPMENT Co. , L t d.		
DESCRIPTION OF DEFECT	Among the customized vehicles whose batteries were relocated, there exists some cases where the clearance between the wiring terminals and the peripheral components are not secured enough, due to the lack of wiring assembly instructions for the inside engine rooms. Therefore, during the usage process, the wiring terminals may come into contact with adjacent parts, leading to a short circuit. And in the worst case, it is possible that the vehicle becomes inoperable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KR-KDH205V	“Hiace” “Regiusace”	2005～2007	10
ADF-KDH206V LDF-KDH206V		2008～2018	118
CBF-TRH200K CBF-TRH200V		2005～2014	76
CBF-TRH221K		2006～2007	6
CBF-TRH223B		2007～2009	25
CBF-TRH226K		2007～2013	3
QDF-GDH206V		2019	2
		TOTAL	240