

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3007	DATE	Mar. 18. 2020
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In single cases a damage of the functional group shift fork / selector sleeve / gear wheel might occur. In case of faults the gear change may not be performed correctly. Under unfavorable conditions, two gears might be engaged at the same time. If two gears are engaged at the same time, the rear wheel may block and / or the teeth of gear wheels might shear off, de-pending on the vehicle speed and the friction coefficient of the road. Subsequently a critical riding situation may not be ruled out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-K16AA	「BMW K1600GT」	2017 - 2019	169
2BL-K16AA	「BMW K1600GTL」	2017 - 2019	138
2BL-K16AA	「BMW K1600B」 「BMW K1600GA」	2017 - 2019	295
		TOTAL	602