

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai -3003	DATE	23 March, 2020
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	On the affected vehicles there is a possibility that the bottom side of the service cover for the fuel pump may get into contact with the connection pipe of the fuel pump in case of unfavourable tolerances and simultaneous application of external forces. In the event of external forces, e.g. by using the rear seats, the connection pipe of the fuel pump may be damaged over the service life of the vehicle and as a result fuel leakage may occur. This can be perceived as fuel odour.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
ABA-95BCNC	Macan	2015	469	
		2016	498	
ABA-95BCNCA		2015	10	
		2016	10	
ABA-J1H1		2017	2174	
		2018	929	
ABA-J1H1A		2017	9	
		2018	8	
ABA-J1H2		Macan GTS	2017	803
			2018	606
ABA-J1H2A	2017		280	
	2018		118	
ABA-95BCTM	Macan S	2015	695	
		2016	419	
		2017	793	
		2018	344	

ABA-95BCTMA	Macan S	2015	103
		2016	37
		2017	36
		2018	8
DBA-95BCTL		2015	234
		2016	254
		2017	193
		2018	52
DBA-95BCTLA	Macan Turbo	2015	284
		2016	178
		2017	95
		2018	20
ABA-J1H3		2017	113
		2018	14
ABA-J1H3A		2017	41
		2018	14
		TOTAL	8912