

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4693	DATE	March-26-2020
MANUFACTURER	HAMANA WORKS CO.,LTD		
DESCRIPTION OF DEFECT	In some fuel tanks , the drain plug is not properly tightened/ attached. Continued use of the tank in such a condition may cause fuel to leak from the drain plug.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FW1AHG	PROFIA	2019	1
2PG-FQ1AJG		2019	1
2KG-FC2ABA	RANGER	2019	1
2KG-GD2ABA		2019	1
2KG-GC2ABA		2019	1
2PG-FE2ABA		2020	1
2PG-FJ2ABG		2020	3
2KG-GK2ABA		2019	4
2KG-FK65FZ	FIGHTER	2020	2
2DG-FQ62F		2019	1
		TOTAL	16