

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No..	4696	DATE	March-26-2020
MANUFACTURER	Topre Corporation		
DESCRIPTION OF DEFECT	In some fuel tanks , the drain plug is not properly tightened/ attached. Continued use of the tank in such a condition may cause fuel to leak from the drain plug.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CYJ77C	GIGA	2019	1
2KG-CYJ77CA		2019	8
2PG-CYJ77C		2019	3
2PG-CYL77C		2019	1
2PG-FRR90S2	FORWARD	2019	12
2PG-FRR90T2		2019	53
2PG-FSR90S2		2019	2
2PG-FSR90T2		2019	3
2PG-FTR90V2		2019	1
2RG-FSR90T2		2019	1
2DG-GC2ABG	HINORANGER	2019	1
2KG-FC2ABA		2019	3
2KG-FC2ABG		2019	28
2KG-FD2ABA		2019	3
2KG-FD2ABG		2019	7
2KG-FJ2ABG		2019	1
2KG-GD2ABG		2019	2
2PG-FE2ABG		2019	2
2KG-FK65FZ	FUSOFIGHTER	2019	2
		TOTAL	134