

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-3008	DATE	APR,01,2020
MANUFACTURE	KWANG YANG MOTOR CO.,LTD. 35, WAN HSING ST.SANMIN DIST. KAOHSIUNG, TAIWAN, R.O.C.. (Importer : KYMCO JAPAN Inc. 6-1-1 Heiwajima, Otaku, Tokyo 143-0006, Japan)		
DESCRIPTION OF DEFECT	Due in the engine oil circuit, the metal inside the oil relief valve rubber is improperly bonded and peels off, which may clog the oil circuit, causing damage to the engine inside due to insufficient oil supply for engine lubrication and, in the worst case, stopping the engine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UNKNOWN	AK 550	2017	15
		TOTAL	15 UNITS