

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-3009	DATE	APR,01,2020
MANUFACTURE	KWANG YANG MOTOR CO.,LTD. 35, WAN HSING ST.SANMIN DIST. KAOHSIUNG, TAIWAN, R.O.C.. (Importer : Kymco Japan Inc. 6-1-1 Heiwajima, Otaku, Tokyo 143-0006, Japan)		
DESCRIPTION OF DEFECT	①Brake lamp does not light due to malfunction of brake switch in front and rear brake lamp electric circuit. As a result, the starter motor does not move and cannot restart, If the front and rear brake switches do not works at the same time during riding scooter, there is a possibility that the vehicle will be hit by a following vehicle. ②Excessive current electric flows in the USB charge controller electric circuit. The USB charge controller may overheat and melt. In the worst case, a fire may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SR30JD	RACING S 150	2017 2018 2019	①②156
SR25JC SR25JD	RACING S 125	2016 2017 2018 2019	①487 ②603
		TOTAL	①643 UNITS ②759 UNITS