

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2978	Date	Apr 02, 2020
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	For the mechatronics of 7 speed DSG automatic transmission, due to the inappropriate housing processing accuracy of the accumulator mounting part, in some cases, a small crack occurred in the housing a large hydraulic pressure fluctuation such as during start-up or traffic jam. As a result, when the hydraulic pressure decreases, the warning light is turned on, the worst case the driving force cannot be transmitted and the vehicle cannot be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-13CAV	VW Scirocco 1.4/118kW	MY2011-MY2013	384
DBA-13CTH		MY2013-MY2014	96
ABA-6RCAV	VW Polo GTI 1.4/132kW	MY2011-MY2013	1,658
ABA-6RCTH		MY2013	1
ABA-6RCGG	VW Polo 1.4/63kW	MY2010	14
DBA-6RCBZ	VW Polo 1.2/77kW	MY2010-MY2014	14,827
DBA-6RCBZW	VW Cross Polo 1.2/77kW	MY2011-MY2013	1,384
DBA-6RCPT	VW Polo Blue GT	MY2014	1
ABA-1KCAV	VW Jetta 1.4/118kw	MY2009-MY2010	2
	VW Golf 1.4/118kw		1
	VW Golf Variant 1.4/118kw		10
DBA-1KCAV	VW Golf 1.4/118kw	MY2011-MY2013	987
	VW Golf Variant 1.4/118kw		1,551
ABA-1KCAX	VW Golf 1.4/90kw	MY2008-MY2010	34
	VW Golf Variant 1.4/90kw		5
DBA-1KCAX	VW Golf 1.4/90kw	MY2010-MY2013	5,997
	VW Golf Variant 1.4/90kw		625

DBA-1KCBZ	VW Golf 1.2/77kw	MY2010-MY2013	6, 191
	VW Golf Variant 1.2/77kw		2, 119
DBA-1KCTH	VW Golf 1.4/118kw	MY2013	34
	VW Golf Variant 1.4/118kw		198
DBA-AUCPT	VW Golf 1.4/103kw	MY2013	1
DBA-1KCAVK	VW Golf Cabriolet 1.4/118kw	MY2012-MY2013	914
DBA-1KCTHK		MY2013	22
ABA-1TCAV	VW Touran 1.4/103kw	MY2010	1
DBA-1TCAV		MY2011-MY2013	3, 836
DBA-1TCTH		MY2013-MY2014	715
DBA-1TCTHW	VW Cross Touran1.4/103kw	MY2013	185
DBA-3CCAX	VW Passat Sedan 1.4T	MY2011-MY2013	1, 515
	VW Passat Variant 1.4T		2, 912
ABA-3CCDAC	VW CC 1.8T	MY2012-MY2013	324
DBA-16CBZ	VW The Beetle 1.2/77kw	MY2012-MY2013	4, 475
DBA-16CBZK	VW The Beetle Cabriolet 1.2	MY2013	5
		Total	51,024