

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3002	DATE	Apr, 2020
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Under certain driving conditions with the accelerator pedal released in the idle approach to a stop the engine management software doesn't assure the idle minimum revs in order to maintain the engine running with consequent possible engine stall event without warning. The engine can switch off approaching a stop at idle, increasing the risk of an accident. However, it is still possible to restart the engine after the problem occurrence.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-47L539	Aventador LP740-4	2017 - 2019	365