

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4725	DATE	06 April 2020
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	(1)The drive sprocket bolt might not be tighten enough so that makes the bolt loosed and the sprocket come off. (2)There is a lever of parking brakes which does not heat-treat due to inadequate process for manufacturing levers. Therefore, parking braking force might decrease.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-C523	「DR595」	2018/8/9~2019/10/8	(1)180 (2)66
YDR-C615	「DR6130」	2018/7/10~2019/10/7	(1)260 (2)106
		2018/7/5~2019/10/4	(1)381 (2)149
		TOTAL	(1)821台 (2)321台