

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-3018	DATE	8/April/2020
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	One of the nuts connecting the brake booster to the firewall is missing. By pressing the brake pedal with high forces the customer might not get the expected brake performance. Risk of reduced brake performance and noise issues. The corrective action is to assemble the missing nut.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[XC40]	2020	28
TOTAL			28