

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3019	DATE	2020/4/9
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain E-Class (213 platform), G-Class (463 platform), S-Class (222 platform), S-Class Coupe and Convertible (217 platform) as well as Mercedes-AMG GT 4-door Coupe (290 platform) vehicles with 4.0L 8-cylinder gasoline-engine the elastomeric material of the oil feed line to the turbochargers might not meet specifications.</p> <p>Due to thermal loading while driving, the oil feed line might exhibit selective leakage. In this case, a contact of leaked oil with hot components in the engine compartment cannot be ruled out. This might lead to a risk of fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
CBA-213089	Mercedes-AMG E63S 4MATIC+	2018	3	
		2019	36	
CBA-213289	Mercedes-AMG E63S 4MATIC+ Wagon		9	
CBA-222187	Mercedes-AMG S63		18	
CBA-222188	Mercedes-AMG S63 4MATIC+		2018	5
			24	
CBA-217388	Mercedes-AMG S63 4MATIC+ Coupe	2019	9	
CBA-217488	Mercedes-AMG S63 4MATIC+ Cabriolet		3	
ABA-463276	Mercedes-AMG G63		649	
4BA-290689	Mercedes-AMG GT63S 4MATIC+		119	
			TOTAL	875